



Photograph No. 1: Worker collecting sample ODC-A-3 from 4 inch pipe (East of column B-19)  
Date: February 2, 2010. Photo taken by: MD



Photograph No. 2: Worker collecting sample P4-A-1  
Date: February 2, 2010. Photo taken by: MD



Photograph No. 3: Locating point using GPS system on roof  
Date: February 2, 2010. Photo taken by: CN



Photograph No. 4: Staked/tagged location on roof  
Date: February 2, 2010. Photo taken by: CN



Photograph No. 5: Worker collecting sample NDC-E-5 (Drill press)  
Date: February 3, 2010. Photo taken by: MD



Photograph No. 6: Worker collecting sample P3-E-1 (Drill press)  
Date: February 3, 2010. Photo taken by: MD





Photograph No. 7: Worker collecting sample from furnace  
Date: February 3, 2010. Photo taken by: MD



Photograph No. 8: Worker collecting sample P3-E-8  
Date: February 3, 2010. Photo taken by: MD





Photograph No. 9: Worker collecting sample equipment sample  
Date: February 3, 2010. Photo taken by: MD



Photograph No. 10: Removed universal waste  
Date: February 9, 2010. Photo taken by: CN



Photograph No. 11: Decontamination of drilling bits  
Date: February 9, 2010. Photo taken by: CN



Photograph No. 12: Decontamination of drilling bits  
Date: February 9, 2010. Photo taken by: CN



Photograph No. 13: Collecting bulk/core samples of wall for PCB analysis  
Date: February 9, 2010. Photo taken by: CN



Photograph No. 14: Constructing containment for asbestos removal in ODC  
Date: February 15, 2010. Photo taken by: CN





Photograph No. 15: Decontaminate drill bits on roof  
Date: February 16, 2010. Photo taken by: CN



Photograph No. 16: East wall of containment in ODC  
Date: February 16, 2010. Photo taken by: CN



Photograph No. 17: South wall of containment in ODC  
Date: February 16, 2010. Photo taken by: CN



Photograph No. 18: North wall of containment in ODC  
Date: February 16, 2010. Photo taken by: CN



Photograph No. 19: West window wall of containment in ODC  
Date: February 16, 2010. Photo taken by: CN



Photograph No. 20: West wall of containment in ODC  
Date: February 16, 2010. Photo taken by: CN





Photograph No. 21: Roof sample location  
Date: February 17, 2010. Photo taken by: CN



Photograph No. 22: Heritage TSCA dumpster  
Date: February 22, 2010. Photo taken by: CN



Photograph No. 23: Heritage TSCA dumpster  
Date: February 22, 2010. Photo taken by: CN



Photograph No. 24: Flat transite sample in ODC  
Date: March 2, 2010. Photo taken by: CN





Photograph No. 25: Abated ACM from pipe in CA-2  
Date: March 2, 2010. Photo taken by: CN



Photograph No. 26: Lead based paint abatement  
Date: March 2, 2010. Photo taken by: CN





Photograph No. 27: Lead Based paint abatement in corridor  
Date: March 3, 2010. Photo taken by: CN




Photograph No. 28: Containment Area (CA-3)  
Date: March 3, 2010. Photo taken by: MD



Photograph No. 29: Containment Area (CA-3)  
Date: March 3, 2010. Photo taken by: MD



Photograph No. 30: Decontamination unit outside CA-3  
Date: March 3, 2010. Photo taken by: MD



Photograph No. 31: Laboratory results posted outside CA-3  
Date: March 3, 2010. Photo taken by: MD



Photograph No. 32: Banner posted outside CA-3  
Date: March 3, 2010. Photo taken by: MD





Photograph No. 33: Water heater for decontamination unit outside CA-3  
Date: March 3, 2010. Photo taken by: MD



Photograph No. 34: Manometer located outside CA-3  
Date: March 3, 2010. Photo taken by: MD



Photograph No. 35: Water tank for decontamination unit outside CA-3  
Date: March 3, 2010. Photo taken by: MD



Photograph No. 36: Plastic tubing hanging out from CA-3 containment wall  
Date: March 3, 2010. Photo taken by: MD



Photograph No. 37: Electrical wires and water outside CA-3  
Date: March 3, 2010. Photo taken by: MD



Photograph No. 38: Dumpsters filled with asbestos waste outside building  
Date: March 4, 2010. Photo taken by: MD





Photograph No. 39: Dumpsters filled with asbestos waste outside building  
Date: March 4, 2010. Photo taken by: MD



Photograph No. 40: Dumpsters filled with asbestos waste outside building  
Date: March 4, 2010. Photo taken by: MD



Photograph No. 41: Lead paint abatement using scrapers  
Date: March 4, 2010. Photo taken by: MD



Photograph No. 42: Lead paint abatement using scrapers  
Date: March 4, 2010. Photo taken by: MD



Photograph No. 43: Lead paint abatement using scrapers  
Date: March 4, 2010. Photo taken by: MD



Photograph No. 44: Containment wall of CA-2  
Date: March 4, 2010. Photo taken by: MD





Photograph No. 45: Workers brushing floor during lead abatement  
Date: March 4, 2010. Photo taken by: MD



Photograph No. 46: Collection of universal waste  
Date: March 4, 2010. Photo taken by: MD



Photograph No. 47: Collection of universal waste  
Date: March 4, 2010. Photo taken by: MD



Photograph No. 48: Lead abatement work area  
Date: March 4, 2010. Photo taken by: MD





Photograph No. 49: Use of water to suppress dust during lead abatement  
Date: March 4, 2010. Photo taken by: MD



Photograph No. 50: Workers on man lift working in a bay area for lead abatement  
Date: March 4, 2010. Photo taken by: MD





Photograph No. 51: Worker scraping friable paint  
Date: March 4, 2010. Photo taken by: MD



Photograph No. 52: Worker cleaning floor during lead abatement  
Date: March 4, 2010. Photo taken by: MD



Photograph No. 53: Water spray and plastics bags used during lead abatement  
Date: March 4, 2010. Photo taken by: MD



Photograph No. 54: Worker cleaning floor during lead abatement  
Date: March 4. Photo taken by: MD





Photograph No. 55: Refrigerant collection unit  
Date: March 10, 2010. Photo taken by: MD



Photograph No. 56: Bobcat (with hammer) breaking the equipment  
Date: March 16, 2010. Photo taken by: MD





Photograph No. 57: Bobcat (with hammer) breaking the equipment  
Date: March 16, 2010. Photo taken by: MD




Photograph No. 58: Broken equipment  
Date: March 16, 2010. Photo taken by: MD





Photograph No. 59: Silt fence and existing chain link fence located north of the site  
Date: March 23, 2010. Photo taken by: MD



Photograph No. 60: Silt fence, ditch and existing chain link fence located north of the site  
Date: March 23, 2010. Photo taken by: MD





Photograph No. 61: Silt fence and ditch located along the north boundary of the site.  
Date: March 23, 2010. Photo taken by: MD



Photograph No. 62: Silt fence located along the chain link fence located north of the site.  
Date: March 23, 2010. Photo taken by: MD





Photograph No. 63: Silt fence bend near the north-east site boundary  
Date: March 23, 2010. Photo taken by: MD



Photograph No. 64: Silt fence bend and existing water near the north-east site boundary  
Date: March 23, 2010. Photo taken by: MD





Photograph No. 65: Existing ditch  
Date: March 23, 2010. Photo taken by: MD



Photograph No. 66: Silt fence , ditch and existing chain link fence located north of the site  
Date: March 23, 2010. Photo taken by: MD





Photograph No. 67: Disconnect in silt fence  
Date: March 23, 2010. Photo taken by: MD



Photograph No. 68: Worker disposing waste in dumpster  
Date: March 23, 2010. Photo taken by: MD





Photograph No. 69: Worker collecting waste bag out of CA-6  
Date: March 24, 2010. Photo taken by: MD



Photograph No. 70: Worker collecting waste bag out of CA-6  
Date: March 24, 2010. Photo taken by: MD



Photograph No. 71: BISCO collecting hard fill samples from the wall of the dock area.  
Date: March 24, 2010. Photo taken by: MD



Photograph No. 72: BISCO collecting hard fill samples from the wall of the dock area.  
Date: March 24, 2010. Photo taken by: MD





Photograph No. 73: Filters used during asbestos abatement work.  
Date: March 24, 2010. Photo taken by: MD



Photograph No. 74: Worker bringing waste from the bag-out exit  
Date: March 30, 2010. Photo taken by: MD





Photograph No. 75: Mercury spill in Room 15.  
Date: April 1, 2010. Photo taken by: MD



Photograph No. 76: Small mercury beads on the floor  
Date: April 5, 2010. Photo taken by: CN



Photograph No. 77: Broom used to sweep the floor  
Date: April 5, 2010. Photo taken by: CN



Photograph No. 78: Small mercury beads on the floor  
Date: April 5, 2010. Photo taken by: CN



Photograph No. 79: Small mercury beads on the floor  
Date: April 5, 2010. Photo taken by: CN



Photograph No. 80: Small mercury beads on the floor  
Date: April 5, 2010. Photo taken by: CN





Photograph No. 81 : Workers removing transite on man lift  
Date: April 12, 2010. Photo taken by: MD



Photograph No. 82: Truck for collecting removed transite  
Date: April 12, 2010. Photo taken by: MD



Photograph No. 83: Workers removing transite on man lift  
Date: April 12, 2010. Photo taken by: MD



Photograph No. 84: Truck for collecting removed transite  
Date: April 12, 2010. Photo taken by: MD





Photograph No. 85: Workers removing transite  
Date: April 12, 2010. Photo taken by: MD



Photograph No. 86: Workers removing transite  
Date: April 12, 2010. Photo taken by: MD



Photograph No. 87: Workers removing transite  
Date: April 12, 2010. Photo taken by: MD




Photograph No. 88: Workers removing transite on man lift  
Date: April 12, 2010. Photo taken by: MD





Photograph No. 89: Tecnica truck for collecting removed transite  
Date: April 12, 2010. Photo taken by: MD



Photograph No. 90: Workers removing transite on man lift  
Date: April 12, 2010. Photo taken by: MD



Photograph No. 91: Opaque glass window seen from the inside of the building  
Date: April 12, 2010. Photo taken by: MD



Photograph No. 92: Foam on glass window as seen from outside of the building  
Date: April 12, 2010. Photo taken by: MD





Photograph No. 93: Decontamination unit of CA-9  
Date: April 12, 2010. Photo taken by: MD



Photograph No. 94: Transite wall  
Date: April 19, 2010. Photo taken by: CN



Photograph No. 95: Transite removal in south wall of ODC  
Date: April 19, 2010. Photo taken by: CN



Photograph No. 96: Transite removal from outer wall in NDC  
Date: April 19, 2010. Photo taken by: CN





Photograph No. 97: Window removal in ODC  
Date: April 19, 2010. Photo taken by: CN



Photograph No. 98: Window removal in ODC  
Date: April 19, 2010. Photo taken by: CN



Photograph No. 99: Removing glass window in ODC  
Date: April 20, 2010. Photo taken by: MD



Photograph No. 100: Removing glasses using man lift  
Date: April 20, 2010. Photo taken by: MD





Photograph No. 101: Removal of transite panel from the roof  
Date: April 20, 2010. Photo taken by: MD



Photograph No. 102: Removal of transite panel from the roof  
Date: April 22, 2010. Photo taken by: MD



Photograph No. 103: HMS building and south area  
Date: April 22, 2010. Photo taken by: MD



Photograph No. 104: Area between trailer and building  
Date: April 22, 2010. Photo taken by: MD





Photograph No. 105: Area between trailer and building  
Date: April 22, 2010. Photo taken by: MD



Photograph No. 106: Area between trailers  
Date: April 22, 2010. Photo taken by: MD



Photograph No. 107: Area near laborers trailer  
Date: April 22, 2010. Photo taken by: MD



Photograph No. 108: Grass near concrete slab  
Date: April 22, 2010. Photo taken by: MD





Photograph No. 109: road next to the building  
Date: April 22, 2010. Photo taken by: MD



Photograph No. 110: Concrete floor located onsite  
Date: April 22, 2010. Photo taken by: MD



Photograph No. 111: Tecnica trailer near site entrance  
Date: April 22, 2010. Photo taken by: MD



Photograph No. 112: Site area in general  
Date: April 22, 2010. Photo taken by: MD





Photograph No. 113: Green debris  
Date: April 22, 2010. Photo taken by: CN



Photograph No. 114: Location of green debris to the north of the building  
Date: April 22, 2010. Photo taken by: CN



Photograph No. 115: Pre-demolition. Looking west at south wall of office area  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 116: Pre-demolition, office area, Panorama of site: Photo 1 of 38  
Date: May 6, 2010. Photo taken by: TH





Photograph No. 117: Pre-demolition, office area, Panorama of site: Photo 2 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 118: Pre-demolition, dock area, Panorama of site: Photo 3 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 119: Pre-demolition, looking north-east, Panorama of site: Photo 4 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 120: Pre-demolition, looking north-east, Panorama of site: Photo 5 of 38  
Date: May 6, 2010. Photo taken by: TH





Photograph No. 121: HMS storage building, Panorama of site: Photo 6 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 122: Pre-demolition, looking north-west, Panorama of site: Photo 7 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 123: Pre-demolition, looking north, Panorama of site: Photo 8 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 124: Pre-demolition, ODC area, Panorama of site: Photo 9 of 38  
Date: May 6, 2010. Photo taken by: TH





Photograph No. 125: Pre-demolition, ODC dock area, Panorama of site: Photo 10 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 126: Shear set up for excavator near ODC, Panorama of site: Photo 11 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 127: Area north of HMS building, Panorama of site: Photo 12 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 128: Area west of ODC (looking north-east), Panorama of site: Photo 13 of 38  
Date: May 6, 2010. Photo taken by: TH





Photograph No. 129: Boiler Room in ODC, Panorama of site: Photo 14 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 130: South side of Boiler room in ODC, Panorama of site: Photo 15 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 131: Boiler room in ODC, looking north, Panorama of site: Photo 16 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 132: Boiler room in ODC, looking north, Panorama of site: Photo 17 of 38  
Date: May 6, 2010. Photo taken by: TH





Photograph No. 133: ODC from boiler Room, looking north, Panorama of site: Photo 18 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 134: Looking at north side of ODC, Panorama of site: Photo 19 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 135: Pre-demolition, looking north-east, Panorama of site: Photo 20 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 136: Pre-demolition, looking east, Panorama of site: Photo 21 of 38  
Date: May 6, 2010. Photo taken by: TH





Photograph No. 137: Pre-demolition, looking south near ODC, Panorama of site: Photo 22 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 138: Pre-demolition, looking south near ODC, Panorama of site: Photo 23 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 139: Looking east from area north of ODC, Panorama of site: Photo 24 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 140 :Looking SE from area north of ODC, Panorama of site: Photo 25 of 38  
Date: May 6, 2010. Photo taken by: TH





Photograph No. 141: Looking SE from area north of ODC, Panorama of site: Photo 26 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 142: Looking south from area north of ODC, Panorama of site: Photo 27 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 143: Looking south from area north of ODC, Panorama of site: Photo 28 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 144: Looking south from area north of ODC, Panorama of site: Photo 29 of 38  
Date: May 6, 2010. Photo taken by: TH





Photograph No. 145: Looking south from area north of ODC, Panorama of site: Photo 30 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 146: Looking at ODC from top of cont. cell, Panorama of site: Photo 31 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 147: Looking east from top of cont. cell, Panorama of site: Photo 32 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 148: Looking further SE from top of cont. cell, Panorama of site: Photo 33 of 38  
Date: May 6, 2010. Photo taken by: TH





Photograph No. 149: Looking further SE from top of cont. cell, Panorama of site: Photo 34 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 150: Looking further SE from top of cont. cell, Panorama of site: Photo 35 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 151: Looking further SE from top of cont. cell, Panorama of site: Photo 36 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 152: Looking further SE from top of cont. cell, Panorama of site: Photo 37 of 38  
Date: May 6, 2010. Photo taken by: TH






Photograph No. 153: Looking further SE from top of cont. cell, Panorama of site: Photo 38 of 38  
Date: May 6, 2010. Photo taken by: TH



Photograph No. 154: Early demolition activities in office area  
Date: May 7, 2010. Photo taken by: TH



Photograph No. 155: Demolition in NDC area (looking west)  
Date: May 11, 2010. Photo taken by: MD



Photograph No. 156: Demolition in NDC area (looking north)  
Date: May 11, 2010. Photo taken by: MD





Photograph No. 157: Demolition in NDC area (looking north west)  
Date: May 11, 2010. Photo taken by: MD



Photograph No. 158: Basin near west edge of the site during rain  
Date: May 13, 2010. Photo taken by: MD



Photograph No. 159: Demolition by excavator with shear in north part of NDC  
Date: May 13, 2010. Photo taken by: MD



Photograph No. 160: Demolition of roof by excavator with shear in north part of NDC  
Date: May 13, 2010. Photo taken by: MD





Photograph No.161: Demolition of roof by excavator with shear in north part of NDC  
Date: May 13, 2010. Photo taken by: MD



Photograph No. 162: Demolition work inside ODC (looking south)  
Date: May 13, 2010. Photo taken by: MD



Photograph No. 163: South-east view of NDC from ODC after partial demolition  
Date: May 13, 2010. Photo taken by: MD



Photograph No. 164: Excavator performing demolition work in NDC area  
Date: May 13, 2010. Photo taken by: MD





Photograph No. 165: Water truck spraying water during demolition work  
Date: May 17, 2010. Photo taken by: MD



Photograph No. 166: Demolition work and dust control measures  
Date: May 17, 2010. Photo taken by: MD



Photograph No. 167: Truck being weighed on scale  
Date: May 18, 2010. Photo taken by: MD



Photograph No. 168: Demolition work in ODC along with water truck and mister  
Date: May 18, 2010. Photo taken by: MD





Photograph No. 169: Demolition work in ODC  
Date: May 18, 2010. Photo taken by: CN



Photograph No. 170: Demolition work in ODC  
Date: May 18, 2010. Photo taken by: CN



Photograph No. 171: Demolition work in ODC  
Date: May 18, 2010. Photo taken by: CN



Photograph No. 172: Demolition work in ODC (looking west)  
Date: May 18, 2010. Photo taken by: CN





Photograph No. 173: Demolition work by Excavator with shear  
Date: May 18, 2010. Photo taken by: CN



Photograph No. 174: Demolition work in ODC  
Date: May 18, 2010. Photo taken by: CN



Photograph No. 175: Piles of waste material (steel and general debris ) at south of ODC  
Date: May 18, 2010. Photo taken by: CN



Photograph No. 176: Truck for hauling waste off site  
Date: May 19, 2010. Photo taken by: CN





Photograph No. 177: Demolished area of building along with piles of removed material  
Date: May 19, 2010. Photo taken by: CN



Photograph No. 178: Scrap metal pile  
Date: May 19, 2010. Photo taken by: CN D



Photograph No. 179: Concrete slab near ODC  
Date: May 19, 2010. Photo taken by: CN



Photograph No. 180: View of ODC from north area  
Date: May 19, 2010. Photo taken by: CN





Photograph No. 181: View of demolished building in NDC  
Date: May 19, 2010. Photo taken by: CN



Photograph No. 182: View of demolished area in ODC  
Date: May 19, 2010. Photo taken by: CN



Photograph No.183: Workers on man lift removing windows from the south wall of P4  
Date: May 19, 2010. Photo taken by: CN



Photograph No. 184: Workers on man lift removing windows from the south wall of P4  
Date: May 19, 2010. Photo taken by: CN





Photograph No. 185: Looking west, SW of HMS building, Panorama of site: Photo 1 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 186: Looking west, NW of HMS building, Panorama of site: Photo 2 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 187: Looking north west, scrap metal pile, Panorama of site: Photo 3 of 33  
Scrap metal pile near HMS building  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 188: Looking NW, scrap metal pile and ODC, Panorama of site: Photo 4 of 33  
Date: May 20, 2010. Photo taken by: TH





Photograph No. 189: Looking north-west, demolition in ODC, Panorama of site: Photo 5 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 190: Looking north, demolition in ODC, Panorama of site: Photo 6 of 33  
Date: May 20, 2010. Photo taken by: TH